

Advisory Information

Advisory Items

- 001 Nearside Headlamp deteriorated but light output not reduced [1.7.5a]
- 002 Offside Headlamp deteriorated but light output not reduced [1.7.5a]
- 003 Nearside rear Direction indicators affected by the operation of another lamp [1.4.A.2h]
- 004 (all) Brake pipe slightly corroded [3.6.B.2c]
- 005 Corrosion underneath and rear suspension arms
- 006 Under-trays fitted obscuring some underside components
- 007 Engine covers fitted obscuring some components in the engine bay

About this document

- 1 This document is a receipt style certificate telling you that an MOT Test pass result has been recorded on The Vehicle & Operator Services Agency's (VOSA's) database of MOT Test results; this may be verified at www.direct.gov.uk/yourmotcheck
 - 2 A test certificate relates only to the condition of the components examined at the time of test. It does not confirm the vehicle will remain roadworthy for the validity of the certificate.
 - 3 Check carefully that the details are correct.
 - 4 Whilst advisory items listed above do not constitute MOT failure items they are drawn to your attention for advice only.
 - 5 For further information about this document please visit www.direct.gov.uk/mot or contact VOSA on 0300 123 9000*.
- *Your call may be monitored or recorded for lawful purposes.